

Outfalls or Points of Discharge

Table 1

Mt. Morris Twp

ID #	Outfall/POD	Receiving Water	Latitude	Longitude	Priority	Priority Explanation
8622251	Outfall	Daly Drain 0420	-83.737965	43.088952	Low	Sampled as #8614504
8622252	Point of Discharge	Daly Drain 0420	-83.739014	43.088353	Low	Sampled as #8614504
8622253	Point of Discharge	Daly Drain 0420	-83.739004	43.088219	Low	Sampled as #8614504
8622254	Point of Discharge	Daly Drain 0420	-83.738982	43.087192	Low	Sampled as #8614504
8627501	Point of Discharge	Hartshorn Branch #1 0358	-83.753108	43.064214	Low	Sampled as #8629773
8627502	Point of Discharge	Hartshorn Branch #1 0358	-83.753081	43.064768	Low	Sampled as #8629773

NOTE: 8622251 is the outlet for Bicentennial Drive. This drive is under GCRC jurisdiction therefore is being removed from Mt. Morris Twp. The Township has 3 point of discharges that drain into 8622251. They have been added above.